


SUPER QIX





LADO SOLDADURA			LADO COMPONENTES
GND	1	1	GND
GND	2	2	GND
GND	3	3	GND
+ 5 V	4	4	+ 5 V
+ 5 V	5	5	+ 5 V
+ 12 V	6	6	+ 12 V
ALTAVOZ MASA	7	7	ALTAVOZ (+)
	8	8	
	9	9	
MONEDERO 2	10	10	MONEDERO 1
2 J. STAR	11	11	1 J. STAR
2 J. ARRIBA	12	12	1 J. ARRIBA
2 J. ABAJO	13	13	1 J. ABAJO
2 J. IZQUIERDA	14	14	1 J. IZQUIERDA
2 J. DERECHA	15	15	1 J. DERECHA
2 J. ACCION	16	16	1 J. ACCION
	17	17	1 J. ARRIBA
AZUL	18	18	VERDE
ROJO	19	19	SINCRONISMO
	20	20	
MASA	21	21	MASA
MASA	22	22	MASA

* NOTA: PUENTEAR EL PIN 11 y 17 EN LADO DE COMPONENTES.

Filiberto

S. Q. IX

SW A

		8	7	6	5	4	3	2	1
MONEDERO 2	1 Moned. 1 Part.	OFF	OFF						
	1 Moned. 2 Part.	OFF	ON						
	2 Moned. 1 Part.	ON	OFF						
	2 Moned. 3 Part.	ON	ON						
MONEDERO 1	1 Moned. 1 Part.			OFF	OFF				
	1 Moned. 2 Part.			OFF	ON				
	2 Moned. 1 Part.			ON	OFF				
	2 Moned. 3 Part.			ON	ON				
CONTINUIDAD	SI					ON			
	NO					OFF			
PARADA JUEGO	JUEGO						OFF		
	PARADA						ON		
PANTALLA	NORMAL							OFF	
	INVERTIDA							ON	
TIPO	MESA								OFF
	MUEBLE								ON

SW B

		8	7	6	5	4	3	2	1
PORCENTAJE	75 %	OFF	OFF						
	70 %	OFF	ON						
	80 %	ON	OFF						
	85 %	ON	ON						
JUGADORES	3			OFF	OFF				
	2			OFF	ON				
	4			ON	OFF				
	5			ON	ON				
	30000-100000					OFF	OFF		
	20000-50000					OFF	ON		
	50000-100000					ON	OFF		
	NO BONUS					ON	ON		
DIFICULTAD	B							OFF	OFF
	A							OFF	ON
	C							ON	OFF
	D							ON	ON

